

**Appendix C**  
**CFA Landfills I, II, and III Photographic Log**





Figure C-1. Sagebrush intrusion on eastside of Landfill II.



Figure C-2. Rock armor at north end of Landfill II.



Figure C-3. Rill on the northeast slope of Landfill II.





Figure C-4. Animal burrows along the eastside of Landfill III.